

AltoUpdate...

MAKE	TRANSMISSION	APPLICATION	YEAR
Various	F4A32, W4A32, F4A33, WA433	Direct Clutch PowerPack® Kit	Various

DESCRIPTION & NOTES...

Premature Direct Clutch Failure is Common Among these New Breed Sport Compact Vehicles...

Make: Mitsubishi, Hyundai, Plymouth

Problem: Due to the introduction of the new breed "high output engines" reports of premature direct clutch failure are very commonplace in these transmission applications. Turbo's, NOS, Computer Enhancements, Tuned Exhaust, are just a few of the modifications available for many of the Sport Compact vehicles. Installation is the same as OE specifications require.

Solution: Alto Kit #108754 contains all of the components to repair the direct clutch pack. The clutch pack capacity has been increased to handle the "high output engines." Also available for this unit is the Alto #059757 end clutch (overdrive) PowerPack®.



ALTO #108754 KIT CONTENTS

Alto#	Qty	Description	Specs.
108740-152	5	Red Eagle Frictions	.059"/1.5mm
108701K152	4	Kolene Steels	.059"/1.5mm
108701K380	1	Bottom Apply Plate	.150"/3.80mm
108762-495	1	Top Pressure Plate	.195"/4.95mm

Alto Way • PO Box 1088 • Atmore • AL • 36504
Tel: 251.368.7777 • Fax: 251.368.7774 • www.altoUSA.com

Clutches and Gears for Automatic and Standard Transmissions

0402001

