

AltoUpdate...

MAKE	TRANSMISSION	APPLICATION	YEAR
Allison	MT640, 643, 650, 653	Main Shaft	Various
DESCRIPTION & NOTES...			

Main Shaft Durability and Performance Alto Part #056379...

The main shaft of this Allison transmission suffers galling on the bushing areas. This will result in metal contamination and too much movement of the components associated with the main shaft. The common practice is to re-work the existing shaft or replace it.

Alto manufactures a complete new main shaft. This is a better alternative than re-working the old main shaft. The quality of this main shaft meets or exceeds the Original Equipment specification. Reference No. 23013456

Installation requirements are the same as OE method of installation.



Alto Way • PO Box 1088 • Atmore • AL • 36504
Tel: 251.368.7777 • Fax: 251.368.7774 • www.altousa.com

Clutches and Gears for Automatic and Standard Transmissions

0310002

